CARBATEC RECHARGEABLE DIGITAL ANGLE FINDER INSTRUCTIONS

WHAT'S IN THE BOX:

- Digital Angle Finder
- Charging Cable
- Instruction Manual

INSTRUCTIONS FOR USE

- 1. Press the power button. "LEVEL" will display in the upper left-hand corner of the display.
- Press the "HOLD" button once to hold the current value on the display. Press again to return to normal function. "HOLD" will be displayed when hold function is active.
- 3. Press the light button to turn on/off the backlight.
- 4. Press the "ZERO" button to set a relative zero. "LEVEL" will no longer display, and the unit is now in relative mode. Hold the power button for 3 seconds to return to absolute mode.

CHARGING UNIT

- 1. Remove the seal on the back of the unit, exposing the USB charging port.
- 2. Carefully connect the included cable to the unit charging port and plug the other end into a USB charger. The charging symbol will flash on the display during charging.
- 3. When the charging symbol on the display stops flashing, charging is complete. Remove the plug and re-seal the port.

RECALIBRATION

Under normal conditions, the Digital Angle Finder does not need recalibration. The device may be recalibrated if the reading becomes inaccurate or the unit suffers a severe impact.

Recalibration requires a level surface with an accuracy of less than .02° and may require multiple attempts to calibrate accurately. Holding the Digital Angle Finder steady while pressing the buttons to recalibrate is essential.







An unlevel surface may produce an inaccurate calibration.

- Place the device upright on a level surface. Press and hold Power and "ZERO" buttons for 5 seconds until the screen displays "CAd1".
- 2. Release the buttons and don't move the unit until the "1" begins to flash.
- With the "1" flashing, rotate the box clockwise, 90° and press the "ZERO" button. The screen will display "CAd2". Don't move the device until the "2" begins to flash.



- With the "2" flashing, rotate the box clockwise another 90°, and press the "ZERO" button. The screen will display "CAd3". Don't move the device until the "3" begins to flash.
- Turn the box another 90° clockwise and press the "ZERO" button. The screen will display "CAd4", Don't move the device until the "4" begins to flash.
- 6. Turn the box clockwise, the final 90°, until it sits upright as at the start. Press the "ZERO" button. The screen will display "CAd5". After 3 seconds without movement, the display will return to 0.00, and the calibration will be complete.







Carbatec Pty Ltd

E info@carbatec.com.au AU 1800 658 111 NZ 0800 444 329 1/364 New Cleveland Road, Tingalpa, Queensland Australia 4173 ABN 84 010 706 242