

STANDARD PARTS KEY

THIS DIAGRAM IS AN OVERVIEW ONLY



You will need:-

Slotted screwdriver

Medium Phillips head screwdriver


Small adjustable spanner

26mm (1") wrench or spanner



1. Power Chisel Extension Arm
2. Clamping Bolt
3. Clamping Nut
4. Adaptor Plate Screw Housing
5. Impact Cam
6. Felt Pad (Oil Reservoir)
7. Lubrication Port

**READ CAREFULLY
AND SAVE**



8. Top Cover
9. Chisel Locking Button
10. Chisel
11. Bushes
12. Button Spring
13. Spring Locator
14. Chisel Holding Spring

15. Example Spacer Washer
16. Self Tapping Screws
17. Grinder Spindle
18. Grinder Collar
19. Emery Friction Strip
20. Adaptor Plate (MIN017)
21. Adaptor Plate Housing Screws
22. Countersunk Self Tapping Screws

Spacer Washers included in the following Power Chisel Kits:-

PCH100

- 3 x M10 flat washers
- 3 x M14 flat washers

PCH101

- 3 x M10 flat washers

PCH102

- 3 x M16 flat washers