


SERVICE BULLETIN



Model: BS-345H
Part changed: Belt tensioner part #80
From: Roller type
To: Pulley type
Reason: To eliminate bearing noise as per factory
Effective: Dec 2017
PO #: 1293X 24 units, 1347X 30 units and 1443X 24 units
Condition: Permanent

Photos

FROM



TO



Parts code:
BAS-350-80-Roller type tensioner
Bas-350-80N-Pulley type tensioner
Belt not changed

Tensioner